

# Headlamp Condensation

**Service Category** Vehicle Exterior

**Section** Lighting (ext)

**Market** USA

Toyota Supports  
 ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2007 – 2009	Prius	

## Introduction

Some 2007-2009 model year Prius vehicles may have an appearance issue and exhibit excessive condensation or moisture on the interior of the headlamp(s). Follow the procedures in this bulletin to address this condition.

## Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
81145-47170	Same	Unit, Headlamp, RH (HID)	1
81130-47160	Same	Unit, Headlamp, RH	1
81185-47170	Same	Unit, Headlamp, LH (HID)	1
81170-47160	Same	Unit, Headlamp, LH	1

## Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
BD9099	R&R Headlamp and Adjust	1.5	811##-471#0	66	55
Combo A		0.6			

### APPLICABLE WARRANTY

- This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.


## Headlamp Condensation

---

### Repair Procedure

1. Confirm buildup of excessive condensation or moisture in headlamp assembly(s).

**Figure 1.**



<b>1</b>	<b>Excessive condensation</b>
----------	-------------------------------

<b>2</b>	<b>Moisture</b>
----------	-----------------

If headlamps have excessive condensation or moisture present, proceed with repair. If condensation or moisture is not present this TSB does NOT apply.

2. Replace the affected headlamp assembly(s).

Refer to the Technical Information System (TIS), applicable model and model year Repair Manual:

- [2007](#) / [2008](#) / [2009](#) Prius  
*Vehicle Exterior – Lighting (ext) Lighting (Ext): “Headlight Assembly: Removal”*
- [2007](#) / [2008](#) / [2009](#) Prius  
*Vehicle Exterior – Lighting (ext) Lighting (Ext): “Headlight Assembly: Installation”*