



F16135

**POINT**

- 1 Inspect the fitting of the front fender and hood, etc., before welding, since this affects the appearance of the finish.