

Vehicle Diagnostic Report

2001 Prius 1NZ-FXE

toyota of bellevue

Printed By: Default User(1)

12/17/2013 3:03:42 PM

Health Check Results All Systems(1 of 1)

System	Monitor Status	FFD	DTC	Curr	Pend	Hist	Perm		Calibration	Update
Engine and ECT	Com	Yes	P0440	X		X			-	
Hybrid Control	-	Yes	P3000	X		X			-	
HV Battery	-	Yes	P3006	X		X			-	
ABS/VSC/TRAC	-	No	C1259	X					-	
Cruise Control	-								-	
EMPS	-								-	
SRS Airbag	-								-	

P0440 - drop tank - charcoal canister
leak

C1259 - other lights were on -

Vehicle Diagnostic Report

2001 Prius 1NZ-FXE

toyota of bellevue

Printed By: Default User(1)

12/17/2013 3:05:03 PM

Diagnostic Trouble Code Report

HV Battery(1 of 1)

Code	Description	Current	Pending	History	Permanent	Summary	Freeze Frame
P3006	Batteries Levels are Unusually Different	X		X		Icon E	Y

Vehicle Diagnostic Report

2001 Prius 1NZ-FXE

toyota of bellevue

Printed By: Default User(1)

12/17/2013 3:05:43 PM

Diagnostic Trouble Code Report

HV Battery(1 of 1)

Code	Description	Current	Pending	History	Permanent	Summary	Freeze Frame
P3006	Batteries Levels are Unusually Different	X		X		Icon E	Y

Freeze Frame Data Report

P3006(Current)(1 of 1)

Parameter	Value	Unit
Battery SOC	53.5	%
WIN	-20.0	KW
WOUT	20.0	KW
Delta SOC	42.5	%
IB Main Battery	-14.26	A
Battery Temperature1	64	F
Battery Temperature2	66	F
Battery Temperature3	68	F
Battery Temperature4	61	F
Battery Inside Air Temp	64	F
Normal Status	Yes	
Pre Onboard Charge	No	
Onboard Charge Status	No	
Outer Charge Status	No	
Cooling Fan Lo	ON	
Cooling Fan Mid	OFF	
Cooling Fan Hi	OFF	
SBL Fan Stop Request	OFF	
Auxiliary Battery Voltage	13.750	V
EQTR Charge Start Sig	OFF	
EQCO Front Relay	OFF	
CCTL	ON	
Battery Bick Voltage 1	17.99	V
Battery Bick Voltage 2	17.98	V
Battery Bick Voltage 3	17.86	V
Battery Bick Voltage 4	17.86	V
Battery Bick Voltage 5	17.83	V
Battery Bick Voltage 6	17.86	V
Battery Bick Voltage 7	17.93	V
Battery Bick Voltage 8	17.89	V
Battery Bick Voltage 9	17.77	V
Battery Bick Voltage 10	17.98	V
Battery Bick Voltage 11	17.83	V
Battery Bick Voltage 12	17.90	V
Battery Bick Voltage 13	17.84	V
Battery Bick Voltage 14	17.79	V
Battery Bick Voltage 15	17.97	V
Battery Bick Voltage 16	17.89	V
Battery Bick Voltage 17	18.07	V
Battery Bick Voltage 18	17.97	V
Battery Bick Voltage 19	18.11	V

Vehicle Diagnostic Report

2001 Prius 1NZ-FXE

toyota of bellevue

Printed By: Default User(1)

12/17/2013 3:09:55 PM

Diagnostic Trouble Code Report Engine and ECT(1 of 1)

DTC Monitors are Complete.

MIL: OFF

Code	Description	Current	Pending	History	Permanent	Summary	Freeze Frame
P0440	Evaporative Emission Control System Malfunction	X		X		Icon E	Y