

**Repair
Procedure**
(Continued)

**B. HV Immobilizer Key Code
Registration Procedure.**

1. Ensure the parking brake is applied and the running mode selector lever is in "P."
2. Insert the ignition key and turn the ignition switch to the "ON" position. Leave the vehicle in this condition for at least 30 minutes.
3. After a minimum of 30 minutes has elapsed, turn the ignition key "OFF."
4. Unplug the charger from the 110V outlet. Remove the red and black charger clamps from the battery.
5. Install the battery positive (+) terminal cover.
6. Install the auxiliary battery cover.
7. Depress the brake pedal, turn and hold the ignition switch to "START" until the green "READY" indicator light remains on and steady. Then release the ignition key.
8. Ensure no trouble lights are illuminated on the Instrument panel or Multi-Information Display (MID).
9. Reset all recorded radio stations. Turn the power on, press "AUDIO." Tune to desired station, press and hold until a beep is heard. Repeat for each station, FM1, FM2, and AM.
10. Reset the clock to the current time.

