



DysonAnalysis.com  
6279 CR 1140

Celeste, Texas 75423

1255001

### Sample Information

Site Celeste, TX  
Area Dennis Coyne Oreno, ME  
Unit Toyota  
Equipment Transmission  
Description 2010 Prius  
Sample Pt Key  
Fluid in Use CVT Trans Differential  
Fluid Grade unknown  
Lst Fluid Change 12/08/2009

0768

### Equipment Information

Equipment Type Gasoline Engine  
Cooled Cooling Source  
Filtered Filter Size  
Lst Filter Change  
Sump Capacity  
Lubrication System  
Lubed Components  
Bearing Types  
Gear Types



### Sample Evaluation

Wear

Physical

Contaminant

Lab

Sample Information			Wear Metals										Additive Metals								Contaminant Metals				
Samp No	Hrs/Miles	Samp Date	Iron	Coppe	Tin	Lead	Chrom	Nickel	Alum	Titan	Silver	Calciu	Magne	Zinc	Phos	Bariu	Molyb	Antim	Silico	Sodiu	Boron	Potas	Vanad		
09120881	11520/11520	12/08/2009	30	19	0	0	2	0	54	0	0	85	1	9	253	7	0	0	106	2	49	0	0		
Watch Advisory Warning Advisory Reference			50	25	20	25	15	10	15	10	10									20	150	50	25	10	
			100	50	40	50	30	20	30	20	20									75	150	100	50	20	

Sample Information		Physical and Other Tests											
Samp No	Samp Date	V40C	V100C	TAN	FLASH	OXID	NIT	KF	TBN	FUEL	SOOT	GLYCOL	vndx
09120881	12/08/2009	23.5	5.1	1.43	310	46	4	258	1.5	1.38	0	0.50	152

Sample Information		Other Tests	Samp No	Comments / Recommendations
Samp No	Samp Date			
09120881	12/08/2009		09120881	Sulfate By Product = 35;
Watch				
Warning				
Ref				

PHONE: 903.413.2071

EMAIL: terry@dysonanalysis.com